			CERN MIT LS AROUND ANISOZ.	WS PDS	germanian and phones	8 64 4			95-CGS-C-1	
AND CORES		ļ.,	and the state of t	activities in the second of th	Triplings arrand names samples	numer Et 1	v.; 1	Da	te: 1/00/2009	j
2	CAPLO GAVAZDEP	WESDA N	ION CONFORMAN	YCE RE	PORT	ref pa	ge 1	of 4	attach: A,	B. (
-	13 Supplier	weined Sign A	PB2-3 switch OFF during	HOT tampa	enture TV	oyeling	Halffür den Legen	or Marketonic Street, organic	and Supergraphic Supergraphics and according	der en en
TION	GGS	i de la companya de l	* Purchase Order N2. N.A.	5 M	odal	8 Suba	ysiom	17 I NA	Procedure/V/gr	k iter
ENTIFICA	PB2 Beard Models Assy		on 9 Orawing Nº. Rev. 11-AMSOZPOS-780.00 /		10 P.N. / C.I. N 11-AMS02PDS		1 [11]		Serial Nº	***************************************
N3CI	17 Next High AMS02 Pewel System Assen	l' Distributton	13 Firstelper Kill		12 P.N. 5	- Annual Control of the Control of t		15	04 2] Sorial IF.	
PV LUNG	18 NON GON	FORMANCE D	Incled During:	1.00 на стругия с т _{акс}	The State of the Land State of	eticetanispisco-cop. Apach	ASSESSED ON THE PARTY OF THE	William State of the second	FMOS	
	RECEIVING INT	P. RUSHUF	CET ASSEMULYMNIED	MINON [FIREL INSPE	спон[_]	Tear X] OTHER	But taken((csg) invary	MONTHELIGH & O
Z	17 Initiator, Dept., Date, Signature R. Grossi, DT/PE, 1/09/2009									
DESCRIPTION	During execution of routine electrical verification during TV cycle, side A PB2 -3 has stopped working. At the mement of malfunction, test conditions were: 5 bit cycle (hot temperature) Side A ON and side B OFF Nominal load (see §10.3.1.8.1 of procedure PDS-PR-CGS-006 is.2) and minimum input voltage = 113V									
1	26 INTERNAL NET Dispositions:									
							West and the second sec			
	DEERATORIER	DCEDURE ENHOR (HARDLING TRANSPOR	ATATION ATERIAL	TENT COL	Barnesagi	Tools			BIGN
1	OPERATOR/PRO	OCEDUAE ERHOH (ATERIAL -	true .	DIPMENT	TOOLS		SW OF	BGN
1	OPERATORARIO OPERATORARIO MIMOR	MAJOR X	PART M Corrective/Preventive A	ATÉRIAL EST	1	Barnesagi	f.,		<u> </u>	BIGN
131 131 YI	OPERATORARIA Classiffcation Mixor REQUEST FO	MAJOR NO POS	Corrective/Preventive A	ATÉRIAL EUONE; LE RAQUIRE ND N2	J n	Barnesagi	TEST	Produced Produce natural city or Unicom	<u> </u>	SUGN
13 12 Y D6	OPERATORMAN Classification Mixor REQUEST FO ES NO OPERATORMAN Partiment:	MAJOR MAJOR DR WAIVER Na PD 5-UV 005 20 P.A.	PART M Corrective/Preventive A 26 Analys 27 Syst. Engineering	ATÉRIAL EUONE; LE RAQUIRE ND N2	J n	Barnesagi	YEST [Produced Produce natural city or Unicom	od documento:	
	OPERATORARIA Classiffcation Mixor REQUEST FO	MAJOR NO POS	Corrective/Preventive A	ATÉRIAL EUONE; LE RAQUIRE ND N2	J n	nuces []	TEST [Produced Produce natural city or Unicom	od documento:	HCIN
	OPERATORARIO Classification Mixtor Mixtor AEQUEST FC ES NO ES NO ES Partinant: Inno: gnature;	MAJOR MAJOR DR WAIVER Na PDS-LW 005 REPA	PART M Gorractive/Preventive A 26 Analys 27 Yes 28 Syst. Engineering	ATÉRIAL EUONE; LE RAQUIRE ND N2	J n	SUCESS ON ON	TEST [27] ON P.M.	horrolati	od documento:	
N N Y & S S S S	OPERATOR/MRI Classification Minor REQUEST FC ES NO espartmant: Inno: gnikturo; to:	OCEDURE ERROR [REALOR DR WAIVER Na PD S - W 00 S Frencht E. 0 1 04	PART M Corrective/Preventive A 26 Analys 27 Syst. Engineering	ATERIAL CUIONS: Ils Require ND N ²	D D	SUCESS SU	27 OK 27 OK P.M. P.M. 100 12 100 10	ther relate	other. 31 6,0, Chauspaint C	42
222 23 25 25 27 Yr De North Date 32 32 32 32	OPERATORING OPERATORING Classification Minor REQUEST FO ES NO OPPORTMENT: OPPORTMENT	OCEDURE ERROR [AMAJOR OR WAIVER IN POS Frencht E. O OG IGHER LEVEL	PART M Corrective/Preventive A V-CGS 26 Analys V3 Syst. Engineering Was 5 OS 7/9/39 CONTRACTOR NRB Olepo	ATERIAL CUIONS: Ils Require ND N ²	D D	SUCESS SU	27 OK 27 OK P.M. P.M. 100 12 100 10	horrolati	other. 31 6,0, Chauspaint C	
222 23 25 25 27 Yr De North Date 32 32 32 32	OPERATORING OPERATORING Classification Minor REQUEST FO ES NO OPPORTMENT: OPPORTMENT	OCEDURE ERROR [REALOR DR WAIVER Na PD S - W 00 S Frencht E. 0 1 04	PART M Corrective/Preventive A 26 Analys 27 Syst. Engineering Alla S CONTRACTOR NEG Dispo	ATERIAL CUIONE; Ile Require ND N2 F 30 positiona (C	D D	Success To John M. J.	27 OK 27 OK P.M. P.M. 100 12 100 10	ther relate	other. 31 6,0, Chauspaint C	42 6
22 23 25 Yi De Nig Sig Da 32 32 32 3	OPERATORING OPERATORING Classification MINOR REQUEST FO REQUES	THE CAUSE OF N	Corrective/Preventive A Corrective/Preventive A Corrective/Preventive A Corrective Contractive/Preventive A Corrective Contractive Contrac	ATERIAL CUIONE; Ile Require ND N2 F 30 positiona (C	d d d d d d d d d d d d d d d d d d d	Galy):	27 OR 27 OR 27 OR 27 OR 27 OR 27 OR 27 OR 27 OR OR OR OR OR OR OR OR	ther relation	od documento:	42 6
22 23 25 YH De Nin 1911 Da 32 32 32 32 33 C	OPERATORING OPERATORING Classification MINOR REQUEST FO REQUES	OCEDURE ERROR [MAJOR MAJOR OR WAIVER IN PDS - W OOS FIRMONE. FIRMONE. GUEST LEVEL INTERCOLOR INTERCO	PART M Corrective/Preventive A 4-CGS 36 Analyse 758 758 758 758 758 759	ATERIAL CUIONE; Ile Require ND N2 F 30 positiona (C	d d d d d d d d d d d d d d d d d d d	Success Of Conty):	27 OK 27 OK	will catlo	od documento: 31 G.C. Chappelm C L'	42 6
22 25 Yi De Na 91 Da 32 32 CO 00 00 00 00 00 00 00 00 00 00 00 00 00	OPERATORIMAN OPERATORIMAN Classification MIMOR REQUEST FO BE NO POPPRIMENT: OPPRIMENT: OPPRIMEN	OCEDURE ERROR [MAJOR MAJOR OR WAIVER IN PDS - W OOS FIRMONE. FIRMONE. GUEST LEVEL INTERCOLOR INTERCO	PART M Corrective/Preventive A Corrective/Preventive A 26 Analyse Y58	ATERIAL CUIONE; Ile Require ND N2 F 30 positiona (C	d d d d d d d d d d d d d d d d d d d	Success 30 July 20 Jul	P.M. P.M. GLOSE GS PAIG	will catlo	od documento: 31 6,0, Chauspaint C L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L 1 L L L L 1 L L L 1 L L L 1 L L L 1 L L L 1	A second

ASI Funt MACHETT Specked in. 21/Sep. 08

ATION PARIA STAMP

C. G. S.

23/09/09

Michael Capell Book GAM/ 1854009

Data:

1 that the same of		TIT		stas
CARGO GAIAZZI	AMS02-PDS	C Rev. 1	: NCR-PDS-CGS-C-139 Date: 1/09/2009	
CARLO GAVAZU SPAČE SUA	NON CONFORMANCE REPORT	R ref Page 2		
	37 CONTINUATION SHEET	The state of the s	CONTROL OF THE PARTY OF THE PAR	-
SUSPECTED CAUSE OF NC	INTERNAL NRB DISPOSITION x DESCRIPTION OF NO		21 Verifications	
FINALLY DETECTED CAUSE	CUSTOMER NRB DISPOSITION CORRECT/PREVENT	TCTIONS	21 Verifications	
REQUIREMENTS VIOLATED	Notaman &			
	FAILURE DESCRIPTION			
range – i.e. 0 or Output voltage for	n has been: send command /receive significant telemetry if statuses set to 1, all analog telemetries to few units digital counts) or all outlets of side A ESEM3A-3 (which is p OV and subsequent impossibility to power e	the minimum		
	FAILURE RECOVERY			
The execution of a 120 performed and, as a resu	V Inlet power switch cycle (ON-> OFF-> It, nominal PDS functionality restored.	ON) has been		Management Constitution of
				Action Contractor
				-
				other contact
				Becklishin
***	and the state of t			Personal sale
				HOLDANDSON
		pro established		CASHWAY
		1		STATE OF THE PARTY
				ETHEROST A
				Dalesteen
		and the second s		Opposition of the last
				Manhead
				The same of
		annico de la companio del companio della companio d		
/				
		1		
1				
		1		
			and the same of th	
			1	



REQUIREMENTS VIOLATED

AMS02-PDS

Doc.Nº: NGR-PDS-CGS-C-139

Rev.: 1

Date: 1/09/2009

NON CONFORMANCE REPORT

ref Page 3 of 4 attach: A

		³⁷ CONTINU	UATION SHEET
SUSPECTED CAUSE OF NO	×	INTERNAL NRB DISPOSITION	DESCRIPTION OF NO
FINALLY DETECTED CAUSE		CUSTOMER NRB DISPOSITION	CORRECT/PREVENT. ACTION

21 Verifications

1. Perform an analysis of the malfunction to identify possible root causes

only failure scenario compatible with such an event is the switch OFF of the auxiliary DC/DC mounted on the board which supplies all PB2 internal circuitry.

As protection intervention is latched, the only way to recover nominal board (and therefore PDS) functionality is to remove PDS internal bus power (nominal voltage 15V).

PDS Internal bus power is provided by the two hot redundant converters of ESEM1A board that can not be commanded; therefore a 120V inlet power switch cycle (ON-> OFF-> ON) has to be performed.

2. Perform additional tests to confirm analysis results and characterize operative condition that influence failure occurrence

- Failure is repetitive provided that test conditions are the same of first recorded event (i.e. nominal load. minimum input voltage of 113V and TRP above 53°) and adequate time is allowed to stabilize PDS internal temperatures
- After failure occurrence, unit functionality is restored by input bus ON-> OFF-> ON cycle and this status is maintained for some minutes before new occurrence even though unit working conditions are set to be the same as before first failure
- Modification of test conditions (namely, TRP temperature decrease or input voltage increase) prevents failure appearance
- No similar malfunction has been recorded on side B boards, though the same operative and environmental conditions have been applied also to these boards

CONSTRUCTOR STATEMENTS
78507310004
MERCHA!

Doc.Nº: NCR-PDS-CGS-C-139

Doc.Nº

Date: 1/09/2009

L	CARLO GAVAZZI SPACE SCA	NON CONFOR	MANCE REPORT	ref Page 4	of 4 attach: A, B, C	
L		37 CONT	INUATION SHEET			-
L	SUSPECTED CAUSE OF NO	X INTERNAL NRB DISPOSITION			21 Verifications	***
	FINALLY DETECTED CAUSE	CUSTOMER NR8 DISPOSITIO	ON GOHRECT/PREVENT, AUTR	OMS		20000000
-	REQUIREMENTS VIOLATED					
3. re	Set-up a teleconf wit sults	th AMS collaboration	to inform about failure a	and analysi	3. OK 2/9/09 DJ	The second secon
3.	1 Continue with test (re	aising input voltage at	114V minimum if necess	ary)	3.1 see Annex A	Section of the second section of the second section of the second
Cla	2 Summarise test res rify which operative s n be found to prevent i	olutions (e.g. load swi	e TVT Functional test p tch OFF or use of redur	wocedure to	3.2 SEE ANNEX B 23/09/09 PJ	CHILDRED SECTION CO. AND AND ADDRESS OF CO.
ne	w PDS WC baseplate	hat are lower than pre temperature	s, based on power diss viously estimated ones-,	ipation data to evaluate	3.3 SEE AUNEX C 23/08/09 PJ	COTHER COMPLETE NO SECRETARION CONTINUES OF SECURIOR SECU
lig	issue ne	QUEST FOR	WAIVER		4, CLOSED 23/08/09 /2	SCHOOLSENSE CONTRACTOR
						SQUAR PROPERTY
	-	Section 1				Consessor/33
						Market Areas
			and the second second			DESAMPROD
			and the state of t			METANOSTA
			and the same of th			Montenano
		and the same of th				CONTRACTOR OF THE PERSONS
		A Comment of the Comm				-
						Contractions
						A STREET, STRE
					- Professional Control of the Contro	March Street
					3.13	
	Jugger .				Marie 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
era d'esta da M						-

Em

ANNEX A TO NCR-PBS-CGS-C-139

Roberto Grossi

2 PAGES

Da: Inviato: Mike Capell [Michael.Capell@cern.ch] mercoledì 2 settembre 2009 12.45

A:

rgrossi@cgspace.it

Cc:

molivier@cgspace.it; plorenzi@cgspace.it; salia@cgspace.it

Oggetto:

RE: undesired protection intervention of the Auxiliary DC/DC during TVTB

Categorie:

CERN SpamKiller Note: -50

Thanks Roberto - this is what I thought (that E3A#3 is not the most loaded) but it is easier to see the numbers. So let me see if I understand the situation:

At +53C on the TRP (somewhere on the baseplate) and 113VDC input the auxiliary DC-DC on E3A #3 overheats and trips. After this no communication with the module is possible and the only recovery possible is to cycle the input power. At +50C TRP or at 114VDC input this doesn't happen. This does not happen for the other seven E3A's. This did not appear in non-vacuum thermal testing.

Is that all correct?

My suggestion is just to continue the test at minimum voltage 114 VDC input on the A side.

I don't think this is worth opening the box and finding the slightly out of tolerance resistor (or whatever) that is causing the problem.

-Mike.

Mike Capell +41 22 767 4706

----Original Message----

From: rgrossi@cgspace.it [mailto:rgrossi@cgspace.it]

Sent: Wednesday, 02 September 2009 12:33

To: Mike Capell

Cc: molivier@cgspace.it; plorenzi@cgspace.it; rgrossi@cgspace.it; salia@cgspace.it Subject: RE: undesired protection intervention of the Auxiliary DC/DC during TVTB

Dear Mike,

when we refer to nominal condition, we implicitly point to Step 4 in the spreadsheet you and Sergio set-up together in the past years for PDS power budget.

In any case, in the attached Excel file yo will find the detils: basically all nominal outlets are ON, all redundant are OFF.

In addition also Outlet 12 of E3B (i.e. CCEB) is also ON (about 400W), but this does not matter as it is at 120V...

Bye, Roberto

```
> What was the total load on PB2 #3?
> What is the load on the other PB2's?
> Call anytime.
> -Mike.
> Mike Capell +41 22 767 4706
> ------>
```

> ----Original Message----

> From: Massimiliano Olivier [mailto:molivier@cgspace.it]

```
> Sent: Wednesday, 02 September 2009 11:12
 > To: Mike Capell; Xudong Cai
 > Cc: plorenzi@cgspace.it; rgrossi@cgspace.it; salia@cgspace.it
 > Subject: PDS: undesired protection intervention of the Auxiliary DC/DC
 > during TVTB
 > Dear Xudong , please be so kind to forward this message to Mike:
 > Dear Mike,
 >
 > during thermal vacuum testing, a malfunction of one PB2 board (namely #3
 > side A) has been recorded during HOT plateau, 53°C -0°C/+3°C (based on a
 > Temperature range Operative HOT for PDS of +48°C with on top a 5°C proto
 > qualification margin), with unit loaded in nominal configuration and
 > supplied with minimum input voltage of 113V.
 > The malfunction results in no power present at relevant 28V outlets and
 > impossibility to receive telemetries / sending command to the board.
 > To recover the situation, it has been necessary to switch OFF / ON the
 > input power supply.
 > No malfunctions have been recorded in the same condition when side B of
 > PDS is operated.
 > Additional investigations have shown that such malfunction can be
> reproduced provided that the same input voltage / environment temperature
 > / load conditions are present.
> In order to try and limit the occurence of this phenomenon, some further
> tests have been conducted and preliminary data show that eitheir reducing
> TRP temperature or slightly incresing applied voltage results in correct
> board (and therefore PDS) operation.
> Specifically, correct operation was obtained with TRP stabilized at 50°C
> (instead of 53°C) with nominal load and minimum input voltage of 113V;
> alternatively, PDS operates well at 53°C with nominal load in case that
> input voltage is 114V (instead of 113V).
> Unfortunately, due to long time required to change operating conditions
> (thermal chamer inertia is extremely significant) and to wait for
> stabilization after modification, only a few attempts could be carried
> Some additional tests have been performed to find the possible root cause
> for such a malfunction, which has been identified in the undesired
> protection intervention of the Auxiliary DC/DC mounted on the board.
> We think a viable solution with no impact on the PDS test schedule could
> be
> found evaluating the operative modes of AMS with you.
> We propose to urgently discuss this topic into details by phone as soon as
> you have time to read this e-mail and decide how to proceed with the test.
> Best Regards
> Massimiliano.
```

>

Introduction

Nominal configuration identification

After the first cycle, used for Full Functional characterisation at HOT= $+53^{\circ}$ -0/ $+3^{\circ}$ C and COLD = -25° -3/ $+0^{\circ}$ C temperatures, the following PDS unit configurations have been adopted for HOT and COLD temperature stabilisation:

HOT temperature

- 1) All PB2 boards switched ON
- 2) All ESEM3-A Nominal outlets switched ON (see Tab. 1)
- 3) Only outlet 12 of ESEM3-B switched ON (no heaters load)

Board	Out. #1 Load [A]	Out. #2 Load [A]	Out. #3 Load [A]	Out. #4 Load [A]	Out. #5 Load [A]	Out. #6 Load [A]	Out. #7 Load [A]	Out. #8
ESEM3A-1	3.0	3.0	1.8	1.5	1.2			Load [A]
ESEM3A-2	3.5	2.9				0.0	3.0	0.0
ESEM3A-3			3.0	1.4	1.8	1.6	1.5	0.7
The state of the s	2.9	2.9	3.4	0.0	0.0	0.0	0.0	2.6
ESEM3A-4	0.0	0.0	0.0	0.0	1.6	1.5	3.0	4.8

Tab. 1: Nominal load configuration for HOT temperature stabilization¹

COLD temperature

- 1) Only PB2 boards #1 and #4 switched ON (default ON boards)
- 2) All ESEM3-A switched OFF (see *Tab. 2*), except for outlet 3 of ESEM3-A#1 and outlet 1 of ESEM3-A#4 (that are connected to JPD loads)
- 3) Outlets 1, 2, 3, 6 of ESEM3-B switched ON (default ON heaters load)

Board	Out. #1 Load [A]	Out. #2 Load [A]	Out. #3 Load [A]	Out. #4 Load [A]	Out. #5 Load [A]	Out. #6 Load [A]	Out. #7 Load [A]	Out. #8
ESEM3A-1	0.0	0.0	0.0	0.0	0.0	0.0	4	Load [A]
ESEM3A-2	0.0	0.0	0.0	0.0	0.0		0.0	0.0
ESEM3A-3	0.0	0.0				0.0	0.0	0.0
			0.0	0.0	0.0	0.0	0.0	0.0
ESEM3A-4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

Tab. 2: Nominal load configuration for COLD temperature stabilization²

¹ This is the nominal configuration used for power budget spreadsheet computation (step 4)

² These are the default ON state outlets, without any load because at -25°C the series thermostats will prevent PDS loading

Routine electrical checks during TV cycles

During all temperature cycling, the following test have been performed continuously to monitor correct unit functionality:

"Periodic" checks (every hour)

- All boards and all outlets switched ON/OFF/ON to check their commandability, using dedicated commands on PDS test GUI SW interface, by either side A or side B CAN bus board
- 2) Verification of all board statuses, relevant temperatures and reference voltage values, using dedicated commands on PDS test GUI SW interface, by both CAN bus boards (see applicable steps of ¶10.3.1.2.3 and ¶10.3.1.2.4 -for side A- and ¶10.3.2.2.3 and ¶10.3.2.2.4 -for side B- of "AMS02-PDS PFM FULL FUNCTIONAL TEST PROCEDURE" PDS-PR-CGS-006 Is. 2)
- 3) Snapshot of PDS test GUI SW interface, showing ESEM1-A analogue tlm. and digital statuses, input stage tlm. and overall OK/NOK statuses / temperature telemetry for all boards
- 4) Input bus voltage variation in the nominal 113-126V, acting on external power supply

"Cyclic" checks (once every plateau, either HOT or COLD, at the end of stabilization phase)

- 5) PDS unit dissipation (see ¶10.3.1.8 -for side A- and ¶10.3.2.8 -for side B- of "AMS02-PDS PFM FULL FUNCTIONAL TEST PROCEDURE" PDS-PR-CGS-006 Is. 2)
- 6) Outlet overcurrent protection tripping (see relevant steps of ¶10.3.1.5.4, ¶10.3.1.5.6, ¶10.3.1.5.8, ¶10.3.1.5.10, ¶10.3.1.5.11 -for side A- and ¶10.3.2.5.4, ¶10.3.2.5.6, ¶10.3.2.5.6, ¶10.3.2.5.11 -for side B- of "AMS02-PDS PFM REDUCED FUNCTIONAL TEST PROCEDURE" PDS-PR-CGS-020 Is. 1)

First failure occurrence

During 5th cycle HOT plateau, with Side A of PDS unit switched ON, PB2-3 board has been found in OFF condition while performing unit dissipation test at 113V input (ref. ¶10.3.1.8.2 of "AMS02-PDS PFM FULL FUNCTIONAL TEST PROCEDURE" PDS-PR-CGS-006 Is. 2). Symptoms of the malfunction were (see Fig. 1):

- Absence of 28V output voltage at all outlets of ESEM3A-3 board (which is powered by PB2-3)
- All board analogue telemetries to low range (around 0V -equivalent to few digital counts)
- All board digital statuses to "High" level (which results in non consistent indications, e.g. board is commanded OFF – though no such command has been sent – but status is ON)

Above described situation is only compatible with complete switch OFF of the aux. DC/DC converter mounted on PB2; in this case, all board internal circuits are not supplied (and therefore not functional) and, as a result, no analogue telemetry is available (0V is read by CAN bus board mounted A/D converter also for "Analog Ref. 2.0V" which is directly related to aux. DC/DC supply voltage) while the pull-up resistor, mounted on CAN bus at digital status line, forces an high state (which is read and interpreted as "NOK" by CAN bus board).

As failure of aux. DC/DC converter board is latched, the only way to restore nominal functionality is to remove aux. DC/DC inlet power; a 120V ON/OFF/ON cycle has to be performed.

After a 120V ON/OFF/ON cycle, unit functionality has been restored and nominal configuration (see *Tab. 1*) could be commanded. Then input voltage has been set to nominal voltage for continuation of functional verifications.




Fig. 1: PDS GUI screenshot after PB2-3 failure occurrence

Additional investigations

After conclusion of routine electrical checks, a dedicated investigation has been started to better identify recorded malfunction in terms of:

- Occurrence
- Relationship with test conditions

In the following paragraphs, the list of performed activity is reported in a chronological order; then, a summary of the derived conclusions is also provided.

Failure repeatability

h.14:45÷15:45 01/09/09: with TRP temperature at 53.9°C, PDS has been left at 113V in nominal condition and failure could be reproduced. It has been noted that after every PB2-3 not commanded switch OFF:

- it is always possible to restore full PDS functionality by means of 120V ON/OFF/ON cycle, without necessity of changing operating conditions (i.e. unit can work with the same electrical input and output voltages and currents that were present before failure)
- some minutes of unit operation are necessary before new failure occurrence.

Apparently, board internal temperatures have to reach again a critical region to allow malfunction occurrence; no significant variation of overall PDS temperature, monitored at TRP level, can be appreciated due to much higher unit thermal inertia.

Effect of input voltage variations

h.15:45÷16:00 01/09/09: with TRP temperature set at 53.9°C, input voltage has been raised at 114V; no unwanted switch OFF of PB2-3 has been recorded

 $h.16:00\ 01/09/09$: with TRP temperature set at 53.9°C, input voltage waveform has been monitored to verify presence of significant undershoot in the 120V->113V transition (see $Fig.\ 2$). Recorded waveform shows a smooth decrease of input voltage; no electrical circuit related causes (e.g. undervoltage protection intervention) for malfunction can be derived from analysis of EGSE power supply provided voltage.

Effect of TRP temperature

h.16:00 01/09/09: cold plate temperature adjusted to have a TRP temperature set at about 50.3°C; during temperature decrease some sporadic switch off have been recorded with input voltage set at 113V

h.20:00 01/09/09: after stabilisation phase with TRP temperature set at 50.3°C, no malfunctions have been recorded with input voltage set at 113V both in a static condition and during 10 variations from 126.5V (max. nominal voltage) to 113V (min. nominal voltage) and vice versa.

Remark: voltage has been measured at unit input level – by means of J300 test points; EGSE power supply was set respectively to 127.9V and 114.7V

Based on above test results, it has been hypothesised that input voltage has no direct influence on failure occurrence; rather presence of a low input voltage results in poorer PB2 converter efficiency⁴ that induces slightly higher PB2 internal temperature.

³ It is further noted that internal 120V bus – downstream PDS input filter – is even much more stable, due to big size input capacitor ⁴ This has been confirmed by power dissipation measurement at 113V w.r.t. 120V or 126V

Fig. 2: PDS GUI screenshot after PB2-3 failure occurrence

To proof this hypothesis, it has been decided to further decrease input voltage below 113V (without tripping input undervoltage protections), while keeping constant TRP temperature at 50.3°C and nominal loads of *Tab. 1*.

h.20:30 01/09/09: Starting with EGSE power supply voltage set on of 114.7V (equivalent to 113V at PDS input), 0.5V downward steps have been applied every about 30 seconds – to allow verification of correct unit functionality in new operating condition.

First failure occurrence has been recorded at 111.7V –set on power supply (equivalent to 109.4V read with multimeter at PDS input) after about 3 minutes from test start

Following power inlet ON/OFF/ON cycle⁵, the descent has been continued with smaller steps of 200mV each.

Second failure has been recorded at 110.3V –set on power supply (equivalent to 108.1V read with multimeter at PDS input) after about 4 minutes from previous failure.

Following power inlet ON/OFF/ON cycle⁵, the descent has been continued with same steps of 200mV each as before.

Third failure has been recorded at 107.5V –set on power supply (equivalent to 105.5V read with ultimeter at PDS input) after about 5 minutes from previous failure.

Following power inlet ON/OFF/ON cycle⁵, no further decrement of input voltage has been applied and a fourth failure recorded after about 3 minutes from previous one.

PDS has been switched OFF and ON again to clear failure effects, input voltage raised in the nominal range and temperature cycling continued as foreseen by the procedure with the 5th cold plateau.

Conclusive summary

The tests which have been performed after first PB2-3 failure detection allow to:

- identify operative condition (input voltage and/or temperature) compatible with nominal PDS functionality.
- clarify that input voltage is not the direct cause of recorded malfunction
- hypothesise as root cause for failure the temperature sensitivity of one component in the input overcurrent protection of the aux. DC/DC of PB2-3 (that is the only circuit which can completely switch OFF converter itself)

⁵ PDS functionality has been restored and unit loaded with *Tab. 1* nominal loads



NCR-PDS-CGS-C-139-Annex-C

Date: 23.09.2009

Page 1 of 3

PDS PFM


Author: Paolo Ruzza

PDS: Evaluation of maximum temperature with updated PDS dissipation

Introduction

Thermal dissipation of PDS has been updated, according to data collected during the qualification test. Actual thermal dissipation obtained during testing is globally 310W vs the former 365W used for the design analyses.

From the previous analyses reported in AMSTCS-TN-CGS-004 MAIN AND TRACKER RADIATOR THERMAL ANALYSIS REPORT Tmax at TRP was 52.3°C



Power on each board has been updated to globally 310W distributed on two different nodes:



NCR-PDS-CGS-C-139-Annex-C

Date: 23.09.2009

Page 2 of 3


PDS PFM

_		Node	New Power	Node	New Power
	E3B	5001	0.00	5301	0.00
1	PB21	5002	0.00	5302	0.00
	E3A1	5003	0.00	5303	0.00
	PB22	5004	0.00	5304	0.00
K	E3A2	5005	0.00	5305	0.00
BUS	PB23	5006	0.00	5306	0.00
m	E3A3	5007	0.00	5307	0.00
	PB24	5008	0.00	5308	0.00
	E3A4	5009	0.00	5309	0.00
	E1A	5010	0.00	5310	0.00
	CAN-A	5011	0.00	5311	6.31
	E3B	5012	1.21	5312	2.12
	PB21	5013	3.09	5313	41.16
	E3A1	5014	2.35	5314	12.18
	PB22	5015	2.88	5315	54.47
B	E3A2	5016	2.50	5316	14.28
BUS	PB23	5017	2.59	5317	40.06
ш	E3A3	5018	2.20	5318	11.73
	PB24	5019	2.84	5319	38.83
1	E3A4	5020	2.41	5320	11.26
L JE	E1A	5021	0.00	5321	17.93
	CAN-A	5022	0.00	5322	6.37

Results

The New Tmax at PDS TRP is 50.0°C on node 2115

PDS TRP






NCR-PDS-CGS-C-139-Annex-C

Date: 23.09.2009

Page 3 of 3

PDS PFM

Temperature spatial distribution on the baseplate, board side (picked @ time with the higher temperature):



The maximum instantaneous temperature calculated in the worst hot case with the maximum PDS dissipation of 310W is 50°C, and is below the maximum tested temperature of 50.3°C to which the PDS unit is able to continuously operate with a 113 V input (see annex B).

Considering the margins taken in the worst hot case definition, the margin attained is sufficient to guarantee the correct operation of PDS on orbit without operational restrictions in nominal configuration.